

## **Independent Slip Testing Services**

+61 (0) 411 600 733 www.sliptesting.com.au


%+64 (0) 279 735 266 www.sliptesting.co.nz

Independent Slip Testing Services

Report Prepared for: All Purpose Coatings
Property Tested: 16 Hawkins Crescent. Bundamba

Client Address: 16 Hawkins Crescent, Bundamba QLD 4304 Australia Date of Test: 18-06-2024 Program #: 4004 Page: 5 of 17

Test Location	Surface Type	Surface Coating	Surface Conditions	Slider Conditioning	British Pendulum Number (BPN)	Slip Resistance Value & Slope Correction Value	TEST RESULTS (Slider96)	
Test Area 4.	ероху	Pipeline Grey	environment: internal (dry area)	P400	67	(SRV)	Mean BPN result after	Classification
F6 Matrix System		coating	slope: <1.5 degrees	86	65	67	adjustments	Classification
			surface: textured		68			
			test direction: anticipated pedestrian travel	lapping	68	(SCV)	67	P5
			other observations: n/a	59	69	n/a		



## COMMENTS:

Temp: 24 deg.C

Weather: Internal- Non Air conditioned Surface Cleaning: Tested as found Testing Instrument W8- Serial #: WM019 Testing Technician: N.Holzberger

^ An individual result both below the result classification and below the mean result minus 20% shall be considered of lower classification

Reported Uncertainty for testing device: 3.0 BPN

ISTS GLOBAL HEADQUARTERS:

124 Hindes Street Lota QLD 4179 Australia

**DISCLAIMER:** ISTS accepts no civil liability or responsibility for any actions whatsoever that may arise as a result of the tests and the publication and issue of this test report. The test report is intended for viewing purposes solely for the named recipient identified above. The slip test report remains the property of ISTS. This report contains privileged and confidential information. The unauthorised reproduction of this report is prohibited.

Accredited for compliance with ISO/IEC 17025 testing and calibration. NATA is a signatory to the APLAC mutual recognition arrangement for the mutual recognition of the equivalence of testing, calibration and inspection reports.





Testing was carried out using the Wet Pendulum Test method using Slider 96 (4S rubber) in accordance with Australian Standard AS 4586-2013 Appendix A.